

## Re: Probelm with new assembled PC

---

*Source:* <http://sci.tech-archive.net/Archive/sci.electronics.repair/2006-09/msg00269.html>

---

- *From:* "JeffM" <[jeffm\\_@xxxxxxxxxx](mailto:jeffm_@xxxxxxxxxx)>
  - *Date:* 4 Sep 2006 10:42:13 -0700
- 

game <[thakurakhil2006@xxxxxxxxxx](mailto:thakurakhil2006@xxxxxxxxxx)> wrote:

when i turn on system nothing display nor even POST screen

T Shadow wrote:

First thing to check is that the M/B isn't shorting on chassis or standoffs.

Always a possibility.

A better group to post to is [alt.comp.hardware.pc-homebuilt](http://groups.google.com/groups/search?q=ingroup:alt.comp.hardware.pc-homebuilt)

Yup. In addition, the simplest configuration gives you the fewest sources of problems.

<http://groups.google.com/groups/search?q=ingroup:alt.comp.hardware.pc-homebuilt+bare-bones+RAM+video+hard->

.