

# Specialised remote control

---

*Source:* <http://sci.tech-archive.net/Archive/sci.electronics.repair/2006-09/msg01486.html>

---

- *From:* "N Cook" <[diverse8@xxxxxxxxxx](mailto:diverse8@xxxxxxxxxx)>
  - *Date:* Wed, 27 Sep 2006 10:09:33 +0100
- 

For medical use with no documentation available anywhere.

Very expensive current version from a different supplier to replace this one, of German manufacture.

There is a small unlabelled switch on the main unit box recessed but accessible by user

and a corresponding one in the battery compartment of the r/c.

Only uses 6 commands of a SAA3004P IC capable of hundreds of commands.

Could the switches change 2 preset banks of codes for operating 2 such sets of kit in close proximity ?

The remote control sometimes fails to operate/alter the device but the visible red LED always pulse on command send. I've now checked that all 4 IR LEDs also always send. Before scoping pulse stream and delving deeper I suspect its a problem with one of these awkward to replace tiny switches on send end or receive end intermittently making or breaking.

As only one set is used I may bypass this altogether, but anyone found such a symptom before.

—

Diverse Devices, Southampton, England  
electronic hints and repair briefs

<http://home.graffiti.net/diverse:graffiti.net/>