

# Sony Trinitron Monitor

---

*Source:* <http://sci.tech-archive.net/Archive/sci.electronics.repair/2007-04/msg00806.html>

---

- *From:* "HankG" <[hank@xxxxxxxxxxx](mailto:hank@xxxxxxxxxxx)>
  - *Date:* Mon, 16 Apr 2007 15:10:41 -0400
- 

I have a 19" Sony Trinitron Monitor which since before its 3rd anniversary, has been getting dimmer and dimmer. In order to use it, I've had to maximize contrast and minimize brightness. The color rendition is fine, the picture is sharp. Just dim. On a dark background, you can see retrace lines. Boy, it's been decades since I've seen them.

Just wondering whether there are any user-serviceable parts that I can replace. Thanks for you input.

Hank