

# Gateway flatscreen repair

---

*Source:* <http://sci.tech-archive.net/Archive/sci.electronics.repair/2008-04/msg01464.html>

---

- *From:* dnatree <[steven@xxxxxxxxxxxxxxxx](mailto:steven@xxxxxxxxxxxxxxxx)>
  - *Date:* Sat, 26 Apr 2008 12:08:39 -0700 (PDT)
- 

This flatscreen model GWT-P42M303 shorted the 15v and I isolated it to pn 4921QP1002B. There are two of these driver hybrid thingees and one is shorted but finding parts seems to be a problem. Any ideas?

.