

Re: Absurd, right? The 30 foot phone line

Re: Absurd, right? The 30 foot phone line

Source: <http://sci.tech-archive.net/Archive/sci.electronics.repair/2008-06/msg00019.html>

- *From:* Franc Zabkar <fzabkar@xxxxxxxxxxxxxxxxxxxxx>
 - *Date:* Mon, 02 Jun 2008 08:16:53 +1000
-

On Sat, 31 May 2008 23:21:58 -0400, "Michael A. Terrell"
<mike.terrell@xxxxxxxxxxxxx> put finger to keyboard and composed:

Some have a tiny webserver to report system status. My cable modem uses
192.168.100.1

Name
WebSTAR DPC2100
Modem Serial Number
201455763
Cable Modem MAC Address
**:*:*:*:*:*:*
Hardware Version
2.0
Software Version
v2.0.2r1244-050319
Receive Power Level
-2.2 dBmV
Transmit Power Level
35.5 dBmV
Cable Modem Status
Operational

This is what my DLink modem tells me:
http://www.users.on.net/~fzabkar/DSL-302G/PopOutPages/DSL_Params.htm

- Franc Zabkar

--

Please remove one 'i' from my address when replying by email.

.