

Re: Buick Rendezvous stops my 2610

Source: <http://sci.tech-archive.net/Archive/sci.geo.satellite-nav/2004-10/1630.html>

From: Max (maxchamberlain_at_REMOVETHISsatx.rr.com)

Date: 10/31/04

Date: Sun, 31 Oct 2004 02:38:00 GMT

On Sun, 31 Oct 2004 00:22:14 GMT, "Anatoliy Kurgan"
<reply_to_group@nomail.net> wrote:

>Hello, q!

>The list of vehicles equipped with special windshields:

>

><http://www.ezpass.com/static/info/exteriors.html>

>

>

>You wrote on Sat, 30 Oct 2004 18:58:38 -0400:

>

> q> It's possible that the Buick has a metalized windshield which limits the

> q> reception of satellite signals.

>

>With best regards, Anatoliy Kurgan.

I believe this also explains why my radar detector doesn't detect in my '01 LeSabre unless it's sitting down on the dashboard at the base of the windshield. Thanks for the link. BTW, the as-of date at that site is Jan. '03, so it's a bit obsolete for '04-'05 models.