

Magellan SporTrack MAP Changed accuracy with new Firmware?

Source: <http://sci.tech-archive.net/Archive/sci.geo.satellite-nav/2004-11/1935.html>

From: Shy One (chitowndale_at_ameritech.net)

Date: 11/29/04

Date: Mon, 29 Nov 2004 10:07:56 GMT

Hi,

I was wondering if anyone else has experienced a change of accuracy with their SporTrack MAP device after upgrading their system?

I upgraded to Firmware Rel V5.34 last month and also re-downloaded the streets information for my area as well.

Since then my location as displayed on the screen has been off by as much as 500 feet. When I am driving down a street, the display shows me driving through people's back yards, in rivers if I am driving next to a river, etc.

It shows me a half block from an intersection when I am sitting at a stop light at the intersection, etc.

These are minor irritants since I still do know where I am, but prior to upgrading to the new Firmware level my display was accurate to within a few feet.

Is this the Firmware or is it the Military sending slightly incorrect data to the GPS unit?

Have I missed something during the upgrade process such as doing some offset adjustment, or such?

Any clues would be much appreciated.

Shy