

Re: 60CSX firmware update – Finally!

Source: <http://sci.tech-archive.net/Archive/sci.geo.satellite-nav/2006-05/msg00367.html>

- *From:* "John Tyson" <johnatyson@xxxxxxxxxxxxxxx>
 - *Date:* Thu, 11 May 2006 21:21:24 GMT
-

"Phil Wheeler" <w6tuh-ng7@xxxxxxxxxx> wrote in message
[news:VWM8g.141\\$9W5.113@xxxxxxxxxxxxxxxxxxxxxxxxxxxxxx](mailto:news:VWM8g.141$9W5.113@xxxxxxxxxxxxxxxxxxxxxxxxxxxxxx)

You may have seen this already, but if you go back and run the webupdater a second time it will load the GPS SW 2.5. Just tried it, and it worked fine. Haven't had a chance to check the differences yet; I hope that it will at least know where 35 is located!

Hmmm .. I never use the webupdater, but do my own.

Maybe this will deal with the AA Lithium issue. I'll give it a shot!

Phil

You need to use webupdater to get the GPS SW 2.5, but having already done the 2.7 update offline you only need the webupdater once.

Unfortunately, it doesn't solve the Lithium battery issue, and 35 is still shown in it's original position initially. Guess I can hope it solves the "tunnel" issue (but I'm not holding my breath). Can't figure out what else they might have done with that upgrade; I sure haven't seen anything!

John