

## Re: Toshiba CF27E50 squashed vert

---

*Source:* <http://sci.tech--archive.net/Archive/sci.electronics.repair/2005-06/msg01616.html>

---

- *From:* "Art" <plotsligt@xxxxxxxxxxxx>
  - *Date:* Wed, 29 Jun 2005 05:54:46 -0400
- 

Replace the associated electrolytic capacitors in the vertical deflection circuit, especially recd or green case. ESR all of them!

"Adam Stouffer" <adam\_stouffer@xxxxxxxxxxxx> wrote in message [news:XMowe.2024\\$At6.1953@xxxxxxxxxxxx](news:XMowe.2024$At6.1953@xxxxxxxxxxxx)

- > Hello all, I acquired a Toshiba CF27E50 tv that seems to have a problem
- > with the vertical. The picture is squashed about 2 inches below the top of
- > the screen.
- >
- > I ordered the schematics and service info from Sams and checked all the
- > voltages on the TA8427K vert amp chip and they were ok. The service info
- > said to replace 4 caps which I did (but with pulls from scrap). So their
- > condition may be questionable.
- >
- > Is it worth looking at anything with a scope or should I just replace the
- > TA8427K and all the caps in the surrounding area? Thanks.
- >
- >
- > Adam

---

• **References:**

- ◆ **[Toshiba CF27E50 squashed vert](#)**
  - ◇ *From:* Adam Stouffer
- Prev by Date: **[Re: Weird Microwave problem – trips breaker when you shut the door!](#)**
- Next by Date: **[Drum machine problems](#)**
- Previous by thread: **[Toshiba CF27E50 squashed vert](#)**
- Next by thread: **[Toshiba CF27E50 squashed vert](#)**
- Index(es):
  - ◆ **[Date](#)**
  - ◆ **[Thread](#)**