

CTC178L2 Chassis, Part ID Help

Source: <http://sci.tech-archive.net/Archive/sci.electronics.repair/2006-11/msg00814.html>

- *From:* "Stevie D" <steve.dumouchel@xxxxxxxxxxxxx>
 - *Date:* 13 Nov 2006 16:48:29 -0800
-

Just need to know what the horiz. drv transistor crosses to, (NTE or ECG). Coolant leak on the board affecting drv trans. and h.out. The original has this # on it: 1101, then under that; -01A. Collector-emitter leakage. Transistor has the physical size of a C2223, (NTE 399).
Cheers, Steve

.