

Re: Help! Crackling noise from speakers.

the paxolin if forcibly prized off leaving the static lines of contacts soldered to the pcb. Used mole grips (lock –jaw pliers) fixed to front anchor points on each switch and desoldered each in tern with hot air gun . Mark 1 to 6 and 2 way or 3 way. One of the function panel lamps was out,not actually o/c. Bad construction bulb wires soldered to copper wire then touching pins (or maybe failed "spot welds") that are soldered to the pcb,whole covered in silicone rubber. Made proper solder joints after pulling off silicone . Covered stem of bulb (where it touches plastic surround) with PTFE tape. 50mA 7 to 8 Volt bulbs.

—
Diverse Devices, Southampton, England
electroni